


M & R Work
undertaken and
completed



Main Entrance



WAITING AREA



WAITING AREA



CORRIDORS



BALVATIKA



BALVATIKA PLAYAREA



RESOURCE ROOM



SOLAR PANEL

Estimated Renovation Work (M&R)

SI No.	Proposed Work	Current Status
1	Renovation of Library(Primary & Secondary) Male and Female staff rooms(Room No-25,05,88)	Layout plan received for Library and Staff Rooms
2	Renovation of CBSE Exam room-11, Admission Room-04, Office & store room 2 & 3.	To be updated by CPWD
3	Provision of shade in assembly area	To be updated by CPWD
4	Signage Board of Vidyalaya	To be updated by CPWD
5	Renovation of Children's Park and Playground in Primary section.	To be updated by CPWD
6	Drainage system of the Vidyalaya	To be updated by CPWD
7	Multipurpose hall for various activities of the Vidyalaya	To be updated by CPWD
8	Guard Cabin at Entrance Gate	To be updated by CPWD
9	Graffiti Art on the walls opposite to Vidyalaya boundary wall at front (During Summer Break)	To be updated by CPWD

M&R WORKS TO BE UNDERTAKEN

1. Iron caging of 02 water coolers and 09 overhead tanks.
2. Mesh (Jaali) in Window of all classrooms except Room No 41,42,43,76,77,78 and 79.
3. Seepage Problems in various rooms (Room No. 17, 29,37,46,57,82,85,).
4. White wash/Patching & Painting of classrooms which could not be done during last Summer vacation.
5. Plastering of Ceiling of various classrooms as identified by CPWD- Room No. 33,45,46,71,75,76,79,80, 81,85,88,91,92,93 etc.
6. Gate Valves (14) required for Overhead water tanks.
7. Wooden Almirah 01 door in both Rooms 77,78
8. Shade on Street light in Morning Assembly area.
9. Broken Green Fibre sheet replacement at Vidyalaya boundary wall.
10. Sewer Problem at back side of Toilet No 38-39
11. Renovation of Washrooms on Gyan Manzil under process
12. Re-Installation of Solar Panels under process

Conducting Structural & Non-Structural Safety audit (Building Safety Certificate), correspondence has already made regarding this Audit to CPWD.