

## BUILDING SAFETY CERTIFICATE

It is certified that visual inspection carried out to the building of Kendriya Vidyalaya No. 04 Mamun Cantt, Pathankot by the undersigned and found, Building are in good state. However, structural safety can not be ascertained through visual inspection.



(Pradeep Kumar)  
AE (Civ)  
AGE S/R-I

### COUNTERSIGNED

*K. Agawal*  
K. Agawal, IDSE  
EE (SG)  
Garrison Engineer

Station: Mamun Mil Str

Dated: 07 Sep 2024

