

**GOVERNMENT OF MANIPUR
PUBLIC WORKS DEPARTMENT**

No. EE/TML/WR/6/18/2025-26/235

Tamenglong, the 2nd March, 2026.

To

The Principal I/C
Kendriya Vidyalaya
Tamenglong, Manipur

Subject: Building Safety Certificate for the Vidyalaya reg.

Ref. No.: 2089-50/KVTML/2025-26/83 dated 19.02.2026.

Sir,

With reference to the above I am to submit herewith the Building Safety Assessment report/Building Safety Certificate **Kendriya Vidyalaya, Tamenglong** duly inspected and certified by Assistant Engineer-I, Tamenglong Division, PWD, Manipur on 02/03/2026 for favour of information and necessary action.

Enclosed: As above.

Yours faithfully,



(Meiringmei Makuthui)
Executive Engineer,
Tamenglong Division, PWD, Manipur.
Executive Engineer
Tamenglong Division
PWD, Manipur.

Copy to:

1. The Chairman, Vidyalaya Management Committee, Kendriya Vidyalaya/The Deputy Commissioner, Tamenglong.
2. Office Copy.

BUILDING SAFETY CERTIFICATE

It is hereby certified that the existing building **Kendriya Vidyalaya School** at **Tamenglong HQ, Tamenglong District, Manipur - 795141** is having block(s)/Floor(s) as per details below:

Details of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)
No. of Floor(s) in the Block	0 Basement, 1 Ground Floor (Administrative Block cum Academic Block)	0 Basement, 1 Ground Floor (Academic Block)	0 Basement, 1 Ground Floor (Academic Block)	

That the building owned/occupied by **Kendriya Vidyalaya, Tamenglong** have complied with the Building safety requirements in accordance with National Building Code Rules and verified by the officers concerned of **Tamenglong Division, PWD, Manipur** on **2nd March, 2026** in the presence of **Shri Hanuman Prajapat, Officiating Principal/TGT Maths, Kendriya Vidyalaya, Tamenglong** and that the building/premises is fit for occupancy for running school with effect from **02.03.2026** for a period of **1(one)** year in accordance with rule and subject to compliance of the specific conditions as appended.

1. Structural Safety – The building has been designed and constructed in accordance with IS codes and NBC provisions, ensuring stability against dead loads, live loads, wind loads, and seismic forces.
2. Lighting & Ventilation – Classrooms and common areas have sufficient natural lighting and ventilation.
3. Sanitation & Hygiene – Adequate toilets, handwashing facilities, and safe drinking water are available, proportionate to student strength, in line with NBC Part IX.
4. Accessibility – The building is barrier-free, with ramps, handrails, and accessible circulation for persons with disabilities, as per NBC guidelines.
5. Space Standards – Minimum floor area per student, ceiling height, corridor width, and classroom dimensions conform to NBC and IS 8827 standards.

Issued on **02.03.2026** at **Tamenglong HQ** by

Signature with Seal:


Assistant Engineer No. I,
Tamenglong Division,
PWD, Manipur.

Name: Pungbatui Newme
 Designation: Assistant Engineer-I,
 Tamenglong Division, PWD Manipur
 Name & Address of Department/ Office:
 Tamenglong Division, PWD, Manipur,
 Duithanlong Ward No. V, Tamenglong HQ
 Tamenglong, Manipur – 795141