

BUILDING FITNESS CERTIFICATE

1. Inspector Name : M. THANG PEI.
2. Building Name : KENDRIYA VIDYALAYA UKHRUL.
3. Building Permit No : Constructed by the Govt. of Manipur,
4. Address : Kashamtang, Ukhrul, Manipur,
PIN - 795142.
5. Description / Classification of Building : PUCCA / PERMANENT.
6. Owner : INDUSTRIAL TRAINING INSTITUTE, Govt. of Manipur.
7. Period for which the certification is issued : 07/05/2019 to 07/05/2029.
8. Nature of Defects, if any
 - a. Foundations & Basement : RCC intact. No defect.
 - b. Superstructure : RCC column, plinth, beam, Lintel E.T.C.
 - c. Doors & Windows : Panelled & Glazed shutters, No defect.
 - d. Wood work : Intact with painting.
 - e. Roof : Ground floor RCC slab roofing.
 - f. Flooring : 1st floor C.I. roofing with ply-wood ceiling.
 - g. Miscellaneous (Crack, etc) : C.C. FLOORING.
 - h. WALL :- BRICK WALLING. : NO crack. The structure is intact.
9. Any Major Defects noticed which will render the building unsafe in any manner : Very much safe.
10. Whether maintenance works have been done properly : Yes.
11. Whether the structure is sound or not for occupancy : The school building was constructed in the year 2008, present age of the building is 10 years. Life of the building is 75 years. As such, the structure is safe and sound for the occupancy.

CERTIFICATE

It is certified that the Building was inspected by me on 07/05/2019 and found to be fit/ until for occupancy, for the period of 10 years. For the reasons stated above.

Place: Ukhrul.
Date: 07/05/2019.

M. Thangpei.

Building Inspection Engineer

Assistant Engineer

Ukhrul Sub-Division

P.W.D., Ukhrul Manipur,