

## GOVERNMENT OF ARUNACHAL PRADESH PUBLIC WORKS DEPARTMENT

OFFICE OF THE EXECUTIVE ENGINEER

Tel: (0360) 2277222, Fax-2277658 E-mail: <u>eepwddmk@gmail.com</u> DOIMUKH DIVISION : APPWD
PAPUMPARE DISTRICT
DOIMUKH-791 112

No.DD/W-82/2021-22//08-09

Dated Dmk., the 21 April 2021.

To,

The Principal,

Kendriya Vidyalaya Kimin

Arunachal Pradesh

Sub:-

Submission of technical inspection and audit report for structural and

non-structural Safety Certificate.

Ref.:-

F.No.1478/07/KVK/2020-21/338 dtd.20/03/2021.

Sir,

With reference to letter No. mentioned above, enclosed find here with the Safety Certificate in respect of Kendriya Vidyalaya, Staff Quarters and Boundary Wall, Kimin, for favor of information please.

1. The Assistant Engineer, Doimukh Sub-Division, APPWD, Doimukh for information.

Enclo:- As stated.

Yours faithfully,

Executive Engineer PWD Doimukh Division,


No.DD/W-82/2021-22/

Copy to:-

Dated Dank., the

April 2021.

Executive Engineer PWD, Doimukh Division,



## GOVERNMENT OF ARUNACHAL PRADESH PUBLIC WORKS DEPARTMENT



Tel: (0360) 2277222, Fax-2277658
E-mail: eepwddmk@gmail.com
eedmkpwd@rediffmail.com

DOIMUKH DIVISION : APPWD
PAPUMPARE DISTRICT
DOIMUKH-791 112

No.DD/W-82/2021-22/

Dated Dmk., the

April 2021.

## TECHNICAL INSPECTION AND AUDIT REPORT FOR STRUCTURAL AND NON-STRUCTURAL SAFETY CERTIFICATE.

Certified that the Kendriya Vidyalaya Kimin Building, Staff Quarters and Boundary Wall, Kimin has been inspected and audited for Structural and Non-Structural Safety and found **STRUCTURALLY SAFE** for the year 2021-22.

Date:

Junior Engineer PWD, Kimin Section,

Assistant Engineer
PWD Doimukh Sub-Division,

Executive Engineer
PWD, Doimukh Division.