

OFFICE OF THE EXECUTIVE ENGINEER DOIMUKH DIVISION, PWD, AP, DOIMUKH DISTRICT: PAPUM PARE



E-mail:eepwddmk@gmail.com

No.DD/W-82/2024-25/05

Dated Dmk., the 15 March 2025

TECHNICAL INSPECTION AND AUDIT REPORT FOR STRUCTURAL AND NON-STRUCTURAL SAFETY CERTIFICATE.

Certified that the Kendriya Vidyalaya Kimin Building, Staff Quarters and Boundary Wall has been inspected and audited for Structural and Non-Structural Safety and found STRUCTURALLY SAFE for the year 2024-25.

Date: 15 March 2025

Junior Engineer

Kimin Section

PWD, AP, Kimin

Junior Engineer,

COMUNH-SUB-DIVISION RC
A.P.W.D.- CIMIN A.P.

प्राचार्य / Principal

कन्त्रीय विद्यालय विक्रिमन (अ. प्र)

Landston Vidyeleva Prusta 14 19

17/3175
17/3175
18.9 HIHITA VMC