



Annexure D

BUILDING SAFETY CERTIFICATE

Dated: 03/04/2025.

It is certified that the existing building KENDRIYA VIDYALAYA, ZIRO (name of the building or premises) at MANIPOLYANG, ZIRO, HAPOLI, LOWER SUBAN STR. A.P. (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	1st floor					

The building is owned/occupied by KENDRIYA VIDYALAYA, ZIRO (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on (date of inspection) in the presence of PAWAN MAURYA, I/C PRINCIPAL, K.V. ZIRO (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 16.08.2015 for a period of years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 3/04/2025 at ZIRO by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : Assistant Engineer,

Name : Rajendra Monty

Designation : Assistant Engineer

Name & Address of Department/ Office: _____

O/o Executive Engineer
PWD: AP, Ziro Division
Secretariat Building Ziro