



भारत सरकार
GOVERNMENT OF INDIA
केंद्रीय लोक निर्माण विभाग
CENTRAL PUBLIC WORKS DEPARTMENT

Speed post/Email



कार्यपालक अभियंता का कार्यालय,
चल्लकेरे सिविल डिवीजन,
भारतीय विज्ञान संस्थान-चल्लकेरे,
कुदापुरा, तालुक-चल्लकेरे,
जिला-चित्रदुर्ग, कर्नाटक-577536

Office of the Executive Engineer,
Challakere Civil Division,
Indian Institute of Science-Challakere
Kudapura, Taluk-Challakere,
Dist-Chitradurga, Karnataka-577536

संख्या. 24 (24) (1) /EE/CCD/2025/166(H)

दिनांक. 15.04.2025

सेवा में/To,

The Principal,
PM Shri Kendriya Vidyalaya,
Amalapura,
Tumkuru-572106.

विषय/Sub:- Issue of safety Certificate of School Building.

Ref:- Your letter No.F.1086/KVT/2024-25/228 dated:21.10.2024

महोदय/ Sir,

With reference to the above Subject, the school building of Kendriya Vidyalaya at Amalapura,Tumkuru has been inspected by the under signed along with Assistant Engineer, CPWD Davangere on 03.04.2025 .It is certified that, the school building of Kendriya Vidyalaya at Amalapura,Tumkuru is structurally safe and safe for habitation.It is observed that a small portion of water proofing on the terrace is found damaged. The same may be attended immediately to avoid leakage in the roof.

Further this is to state that, the building and other structure are to be maintained regularly by the school authority to keep in safe and habitable condition.

This Certificate is valid for the period of 2(two) years from the date of issue of this letter.

भवदीया/ Yours faithfully,

कार्यपालक अभियंता / Executive Engineer
Challakere Civil Division, Challakere
Kudapura, Challakere,
KARNATAKA - 577536

Copy to: -

1. Assistant Engineer, CPWD Davangere

Mr. Sandeep
Office for n/a
19/4/25

कार्यपालक अभियंता / Executive Engineer

