


Summary Report

- The structure is safe for accommodating students provided the suggestions and recommendations are addressed and properly implemented.
- The school lacks an emergency fire exit plan and maps. It is suggested to have a fire exit plan and display at critical locations to ensure safety during emergency/ fire conditions.

Date: 30.03.2021



Dr. Sandeep Chaudhary
Professor
Department of Civil Engineering
Indian Institute of Technology Indore
Simrol, Indore 453552