



Ph. No-03842-268817, E-mail ID: nez2eescd.cpwd@nic.in

Website: <https://cpwd.gov.in>

संख्या :- 24(1)DB/EE-SIL/2023-24/ 418

दिनांक: सिलचर: 22/06/2023

STRUCTURAL SAFETY CERTIFICATE

It is certified that the Kendriya Vidyalaya School building along with Staff quarter and boundary wall at Assam University, Silchar executed by Central Public Works Department. It is further certified that the building along with Staff quarter and boundary wall is structurally safe for Academic year 2023-24 with regular routine maintenance of the premises.

कार्यपालक अभियंता
के.लो.नि.वि., सिलचर

प्रतिलिपि:-

✓ (1) The Principal, Kendriya vidyalaya, Assam University, Silchar w.r.t.yr. Ref. No. – F.2333010/KV AU SIL/2023/Admn/729 dt. 19/05/23.

(2) The Executive Engineer, Assam University, Silchar for information please.


कार्यपालक अभियंता, सिलचर
Executive Engineer
Silchar Central Division
CPWD, Silchar.