

BUILDING SAFETY CERTIFICATE

No. 23(164)/EECLT/2025/

Dated: 19.09.2025

Certified that the existing building **Kendriya Vidyalaya, Mahe School building** (name of the building or premises) at **Chembra P.O), Paral – 670 671** (address) comprised of buildings as detailed below

1. Basement below Ground floor one wing
2. Ground floor on front and one side wing only
3. First floor front and both side wings
4. Second floor Front portion and one side wing only

Owned/occupied by **Kendriya Vidyalaya, Mahe** (name of the Institution) have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of **CPWD** (Name of Department/ Govt.) on **09.09.2025** (date of inspection) in the presence of **Shri. Gireesh Kumar N, Principal, Kendriya Vidyalaya, Mahe** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes **XII** (XI XII) with effect from **19.09.2025** for a period of **One Year** in accordance with rule and subject to compliance of the specific conditions as appended.

1. The terrace and sunshade top of the building is to be cleaned regularly to avoid water stagnation.
2. Maintenance and repair including clearing of grass and jungle from the premises, cleaning of blockages from the inlet mouths of rain water pipes, desilting of drainages to be done periodically.
3. Internal and external paintings of walls to be done at required intervals.

Note: 1. This certificate does not cover the Electrical installation.

2. This certificate is subject to the Fire NOC from the Fire & Safety Department.

Issued on 19.09.2025 at 12.30 PM by



Signature with seal:

Name:

Designation:

Name & Address of Department/Office:

(Handwritten signature)

P.K. Jose
Executive Engineer
Calicut Central Division
CPWD, M.S. Babu
Kallai, Calicut - 67300