Tele /Fax: 03222-232138/232010 E mail ID: afkalai4-mes@nic.in

Garrison Engineer (AF) Kalaikunda Military Engineer Services Post-Kalaikunda Air Field Dist-Paschim Medinipur PIN-721303

2168/KV Corrs/ 121 /E2

PM Shri KV No-1 AFS Kalaikunda

06 Jul 2024

BUILDING SAFETY CERTIFICATE AND PORTABLE WATER SAFETY CERTIFICATE FOR OUR VIDYALAYA

- Ref your letter No F 25201/KV1/KKD/2024-25/ADMN/61 dt 24 Jun 2024. 1.
- The structured stability of the building can be ascertained only after testing i.e by Non Destructive Test (NDT) of various members of the structure for which as amount Rs 1.5 Lakhs is required to be sanctioned.
- However, pending sanction of the above said work, the structure is safe from visual inspection point of view, as no major damage is visible.
- Apart from Ser No 3, the following points has been observed during inspection and needs to be ascertain by projecting of special repair work subject to release of funds for further repair :-
 - Seepage from the roof found at various location of several No of buildings. (a)
 - Flooring found broken & damaged at No of places in passage, class rooms etc. (b)
 - Plaster found deteriorated/rusted from walls at various places. (c)
 - Seepage/leakage found in children toilet. (d)
 - Painting found very old & colour faded. (e)
 - Door window found broken in various classroom including several other nature of (f) defects.
- It is certified that water used in your school is safe for usage and it is tested on regular intervals through PHE department /SMC of this AF Stn.
- This is for your info and necessary action n please. 6.

(Gautam Kumar)

AE (Civil)

AGE 'T'

for Garrison Engineer (AF) KKD

Copy to :-

AGE (B&R)-I Kalaikunda

AGE (E&M) Kalaikunda

for info please.