



EDUCATION DEPARTMENT
GOVERNMENT OF SIKKIM
GANGTOK

Memo No.- 021.....


Date- 21/01/2025

BUILDING SAFETY CERTIFICATE


This is to Certify that a physical inspection of **Kendriya Vidyalaya N.H.P.C Singtam**, in **East Sikkim**, was conducted on 19th January 2025 by the field engineer of Education Department East-I, where it was found that the above mentioned school had a single building which comprises of two storeyed RCC structure where two floors from ground floor to first floor are being run for academic purposes, There are 44 rooms including toilets, the built in plinth area is 77,885.28ft² . It may be noted that the entire school was covered by the debris from the flash flood of 4th October 2023, however clearing of debris is being done to a potentially 90% of the entire area,

The visual inspection revealed that the columns, beams and slab did not have cracks or shear stress of any kind, the partitions had cracks, there are minor damages to the school building which needs to be repaired and rectified. Hence, this certificate is issued purely on the basis of visual assessment as the integrity of the school building could not be ascertained technically, due to the lack of proper equipments.

This certificate is valid for a period of six months only from the date of issue.


Junior Engineer, (Gtk)
Education Department
Govt. of Sikkim
EDUCATION DEPARTMENT
GOVERNMENT OF SIKKIM

1. Superintending Engineer,
2. Office copy


Assistant Engineer, (Gtk)
Education Department
Govt. of Sikkim
ASSISTANT ENGINEER (EAST-I)
EDUCATION DEPARTMENT
GOVERNMENT OF SIKKIM