एन पी सी सी
NPCC
PROJECT EXCELLENCE SINCE 1957
A MINIRATNA CATEGORY-1 COMPANY

नेशनल प्रोजेक्ट्स कन्सट्रक्शन कारपोरेशन लिमिटेड
(भारत सकार का उद्यम)
National Projects Construction Corporation Limited
Govt. of India (Ministry of Jal Shakti) Undertaking
Northern Zone, 822-A, Gandhi Nagar, Jammu, J&K - 180004
Tel. No. 0191-2459553 E-mail : npcc.jammu@gmail.com

Structural Safety Certificate

Name of Work:-Construction & Development of Kendriya Vidyalaya at Sunderbani, Rajouri, Jammu & Kashmir

Date of Completion:-

Construction Agency:- M/s Winners Construction Pvt. Ltd.

As per our Architect ARHTA & ASSOCIATES letter dated 03.11.2025, we are hereby submitting the Structural Stability Certificate received from our architect for the Kendriya Vidyalaya Sunerbani.These documents reflect the as built status of the structure and has been verified and certified by the concerned structural engineer.

Date:-

R Kumar

Zonal Manager
NPCC Ltd.
Northern Zone, Jammu

Engineer (C)

क्षेत्रीय प्रबंधक / Zonal Manager
एन.पी.सी.सी. लिमिटेड / N.P.C.C. Limited
(भारत सरकार का उद्यम) / (A Govt. of India Enterprises)
उत्तरी क्षेत्र कार्यालय / Northern Zonal Office
जम्मू-160004 (जे & के), भारत / Jammu & Kashmir, H.P.

Enclosed:- Structure Safety Certificate

Scanned with OKEN Scanner

Arhta
Architect
Harish
Tripathi
&
Associates

Date: 03 Nov 2025

To,

The Zonal Manager
Jammu & Kashmir,
NPCC Ltd
Northern Zone

Name of Work: Construction and Development of Kendriya Vidyalaya at Sunderbani, Jammu & Kashmir.

Sub: Submission of Structural Certificate issued from structural consultant along with Built up and GFC Drawings.

Dear Sir,

We are hereby submitting the Structural Stability Certificate received from the Structural Consultant for the Kendriya Vidyalaya, Sunderbani project. Along with this, please find enclosed the final built-up drawings and Good for Construction (GFC) drawings for your kind perusal and necessary action.

These documents reflect the as-built status of the structure and have been verified and certified by the concerned structural engineer. We request you to kindly acknowledge the receipt and confirm if any further documentation is required from our end.

Warm Regards

For **Architect Harish Tripathi & Associates**

Principal Architect
Dr. Harish Tripathi

224, Sukhdev Vihar,
Near Escorts Heart Institute
New Delhi-110025 (India)
Phone : +91-11-41627270
Mobile : 9811045628
Email : arhta1@gmail.com
htji@yahoo.com
Website : www.arhta.com

Scanned with OKEN Scanner

D & R CONSULTANT

100A,3rd Floor, Bharat Nagar, New Friends Colony, New Delhi-110025
office Ph: No. 011-40582616,9810592984, 9810592985 Email: revati_raman1@yahoo.com

CERTIFICATE OF STRUCTURAL STABILITY

(To whom so ever it may concern)

This Stability Certificate is for Proposed Development of Kendriya Vidhalaya at Sunderbani, Jammu & Kashmir.

Dead load, live Load and Seismic load as per the guidelines laid down by the latest B.I.S standards i.e. IS: 456-2000, IS: 800-2007, IS:1893-2016 (Earthquake Code) and IS:875:20215 Part 3 (Wind Code , and National Building Code (NBC 2016) is Considered as detailed in structural design basis.

Structural Design and Drawings for foundation have been prepared based on the soil report/ recommendations by Engg. Research Labs, Vide Soil report number TC9140210000257F dated: 24-12-2021.

We affirm that the structure is stable and withstand designed loads as mentioned above and is structurally safe and stable to the best of our knowledge and professional experience.

REVATI RAMAN SINGH
Chartered Engineer (India)
M-130380-5

REVATI RAMAN SINGH

(D & R CONSULTANT)

Scanned with OKEN Scanner

COMPLETION REPORT

1.	Name of Work	: Construction & Development of Kendriya Vidyalaya at BSF **Sunderbani Jammu and Kashmir**
2.	Amount of AA & ES and Date	: **AA&ES:- Rs.2493.04 Lakhs – (110112-61/2017-KVS(HQ)/(Wk-1)/2804 dated 24.06.2022**
3.	Date of Commencement	: 20.10.2022
4.	Date of Completion	: 06.11.2025
5.	Date of expiry of defect liability period	: 05.11.2026

a) Certified that the above work has been completed in all respects as per the sanctioned scope and specifications laid down.

b) The handing/taking over note is enclosed.

c) Sub-standard/defective work as and when pointed out by KV/KVS authorities shall be rectified by us during the defect liability period.

Station: Sunderbani (J&K)

Date:

As per the observation report submitted by the school level committee, completion report is issued subject to the following accomplished and yet to be executed parameter. (Annexure attached).

SIGNATURE OF PROJECT MANAGER/NPCC REPRESENTATIVE WITH DATE AND SEAL

Engineer (civil)

COUNTERSIGNED BY 25/11/2025

PRINCIPAL OF KENDRIYA VIDYALAYA WITH DATE AND SEAL

प्राचार्य/Principal
केन्द्रीय विद्यालय/Kendriya Vidyalaya
सी.सु.व.परिसर सुंदरबनी/BSF Campus, Sunderbani
ज.व.क./J&K 185153

Scanned with OKEN Scanner

Construction & Development of
Kendriya Vidyalaya at Sunderbani Rajouri

Jammu & Kashmir

Project Handing /Taking over Documents

National Projects Construction Corporation Ltd. (Govt. of India Enterprises)
Northern Zone
Jammu

Handed over by
NPCC Ltd.
Construction Agency

25/11/2025
प्राचार्य/Principal
केंद्रीय विद्यालय/Kendriya Vidyalaya
सी.स.व.परिसर सुंदरबनी/BSF Campus, Sunderbani
ज.व.क./J&K 185153

Taking over by
Principal K.V Sunderbani
Owner

Scanned with OKEN Scanner

HANDED OVER/TAKING OVER of Construction & Development of Kendriya Vidyalaya at Sunderbani Jammu & Kashmir

The Construction of Kendriya Vidyalaya campus comprises of Type 'A' School Building, including sports facilities, Assembly area, Boundary Wall and other allied structures including development work at Sunderbani BSF campus has been completed by M/s National Projects Construction Corporation Limited as per the AA/ES issued by KVS vide letter no **(110112-61/2017-KVS(HQ)/Wk-1/2804 dated 24.06.2022). The date of completion and handed over the works is** 06.11.2023 **subjected to the Defects Liability Period (DLP) of 12 months as per agreement clause upto**

The documents related to the work are as per the following Annexures (enclosed)

1) **Annexure –A:- As built/completion drawings.**
2) **Annexure –B:- Inventories.**

As per the observation report submitted by the school level committee, completion report is issued subject to the following accomplished and yet to be executive parameter. (Annexure Attached)

National Projects Construction Corporation Ltd. (A Govt. of India Enterprise) Northern Zone Jammu

Handed over by
NPCC Ltd.
Construction Agency

21/11/2023

प्राचार्य/Principal
केंद्रीय विद्यालय/Kendriya Vidyalaya
सी.सु.प.परिसर/BSF Campus, Sunderbani
ज.व. PIN-185153

Taking over by
Principal, K.V Sunderbani
Owner

Scanned with OKEN Scanner

WINNER CONSTRUCTIONS PRIVATE LIMITED
402, PRESTIGE CHAMBERS, 15A/1, W.E.A., KAROL BAGH, NEW DELHI-110005
PHONE : 91-11-25717072, 25763046 FAX : 91-11-25757946
E-mail : winnerconstruction@rediffmail.com, winnerconst@gmail.com
ISO 9001 : 2008

WCPL/NPCC/KVS/25-26/Jammu/1046

Dated:- 04/11/2025

TO WHOMSOEVER IT MAY CONCERN

It is to certify that all Internal and External Electrical works has been done as per standard norms and it is fully safe to be used.

Sr. Electrical Engg.

M/S WINNER CONSTRUCTIONS PVT.LTD.
(Authorized Signatory)
WINNER CONSTRUCTIONS PVT. LTD.

Scanned with OKEN Scanner

General Observations in New School Campus. Dt. 25.11.2025 (ANNEXURE – I)

1. Safety and Security: The mandatory boundary wall in front of the staff quarters has not been constructed, posing a significant risk to the safety and security of students and staff.
2. Volleyball and Badminton court yet to be developed.
3. Athletic Facilities: The running track is still to be developed by the construction agency.
4. Level dressing is to be done as required.
5. Construction agency to provide training of Electric Sub Station, Pump House and Fire Fighting Equipments functioning to the deployed employees of the school.
6. Footing of boundary wall not made.
7. Paver work not completed properly and upto the mark.
8. Finishing and cleanliness work yet to be done.
9. Poor-quality door handles have been installed; several handles were found broken during shifting.
10. Supporting Toilets handles has not been installed as per standard ~~KVS~~ Norms made for Divyangjan.
11. Staff Quarters Safety: The balconies on the first floor of the staff quarters are uncovered, which are unsafe for kids.
12. BALA Provision: The provision for the Building as Learning Aid (BALA) project, as stipulated in Point No. 12 of KVS HQ Letter No. 110112-61/2017-KVS(HQ)/(Wk-I/2804) dated 24.06.2022, has not been executed by the agency.
13. Construction agency to submit final settlement of construction work to the competent authority. before ✓ completion report; final

Observed By:-

1. **Sh. Chandan Maurya, TGT(WE)** 25/11/25
2. **Sh. Satish Kumar, TGT(Math)** 25/11/25
3. **Sh. Manoj Kumar, TGT (Lib.)** 25/11/2025
4. **Sh. Manish Kumar, PGT (CS)** 25/11/25

25/11/2025

(Ram Naresh Meena)
I/c Principal

केन्द्रीय विद्यालय/Kendriya Vidyalaya
बी.एस.एफ. परिसर सुंदरबनी/BSF Campus, Sunderbani
ज.व.क./J&K 185153

Scanned with OKEN Scanner

Office of the Director Fire & Emergency Services, J&K
Jammu/Srinagar

The Principal
Kendriya Vidyalaya BSF
Sunderbani

No: DFES-FP/9/2022-04(CC-7079422)1644 Dated: 18.09.2025

Sub: Fire Safety Certificate.

Ref: Your Letter No.2157/350/K.V.S.B./2025-26/2166 dated: 30.08.2025.

The spot inspection of above said school was got carried out by the inspecting officer of this department. During inspection, it was found that the management has installed 06 Nos. of Hose Reel Hose and 24 Nos. of First Aid Fire Extinguishers in their school premises. Besides this, one underground water storage tank of 80 KL capacity is also available. Moreover, the school is about 03 Km away from Fire and Emergency Station Sudnerbani and is approachable for fire appliances in case of any emergency. Since the school is already functioning, as such, the management can proceed ahead for operation subject to adopt the following fire safety measures/ guidelines in letter and spirit forthwith:-

1. 01 No. of CO_2 Type fire extinguisher of 4.5 Kg capacity should be provided near main electric switch board panel in addition to already existing fire extinguishers.
2. All exit/entrances should be kept open and free from any obstruction for quick and safe evacuation of inmate during any emergency.
3. First Aid Firefighting system installed in the school building should be checked periodically. Staff and management should be fully trained in handling / operating of firefighting system installed in the school building.
4. All electric installations existing in the building should be concealed conduit type.
5. One additional emergency exit/staircase serving all floors should be provided in the building for quick and safe evacuation of students/staff in case of any emergency.
6. Manual Operated Electric Fire Alarm System should be installed in the school building.
7. All class rooms and examination halls having seating capacity for more than 45 students need to be provided with two exits.
8. The corridor of the building shall not be used for any kind of storage.
9. No Hazardous material should be kept inside of the school premises (especially LPG cylinder, Petrol and Diesel etc.). Any deviation found in this regard, this clearance will be treated automatically withdrawn/cancelled.
10. The management shall be wholly and solely responsible for keeping the firefighting system in working condition 24x7 and safe evacuation of its students during any mishap.
11. At present school is triple storied. As such, no addition / alteration should be made by the school management in the existing structure without prior information from this department. Any deviation found in this regard, this clearance will be treated automatically withdrawn/ cancelled.
12. The department can make a surprise visit to your school at any time. During the visit, if the firefighting system (i.e. existing as well as proposed) found defunct and deviation, this clearance issued shall be treated automatically withdrawn/cancelled.
13. **This clearance shall be subject to outcome of any dispute/investigation/enquiry/trial if any, pending before any Court of Law/investigation agency. This clearance shall not confirm any title upon the person/company in whose favour it is issued. Further, the status with regard to land shall be the responsibility of the concerned registering authority.**
14. **The instant clearance is strictly for adoption of fire safety measures/guidelines of the occupancy only and not for authentication of any other claim.**
15. **The validity of this clearance shall remain in force for one year and same needs to be renew yearly after inspection/checking of entire firefighting system (i.e. existing as well as proposed) installed in the school building. However, before granting permission/ recognition/extension or renewal thereof, the authority concerned shall satisfy himself in terms of conditions laid down in SRO-123 of 2010 and SRO-292 of 2018, issued by Education Department with regard to physical facilities and also ensure the fire safety measures/guidelines given to the proprietor by this department are fully complied with.**

18/09/2025

Director
Fire & Emergency Services, J&K
Jammu/Srinagar

Jal Jeevan Mission

Har Ghar Jal

Har Ghar Jal
Jal Jeevan Mission

S.D. Water Testing Laboratory, Naushera

Sub division Office, Jal Shakti Department, Naushera. Pin-185151 (Test Address only)

Download Print

Test report

Sample Id:	U722368S34780961

User Information

Name:	Vinod Kumar	Mobile:	9697120918
Email:	lichensremedies@gmail.com	Pin Code:	0
Full Address:	Village- Not available , Gram Panchayat- Not available, Block- Not available, District- Rajouri, State- Jammu & Kashmir		

Sample description

Source of Sample:	Others, location :	Village:	Bhajwal
Gram Panchayat:	Bajwal Upper-A	Block:	Sunderbani
District:	Rajouri	State:	Jammu & Kashmir
Address:		Remarks:	Junior wing drinking water, KV School Sunderbani
Latitude:	33.156568	Longitude:	74.241945

Date & time of sample collection

12.02.2026 | 10:12:00 AM

Date & time of sample received in lab

12.02.2026 | 06:46:00 PM

Date & time of sample analysed

13.02.2026 | 06:49:00 PM

Date & time of report generation

16.02.2026 | 06:54:03 PM

Test results

S. No.	Parameters tested	Unit of measurement	Requirement (acceptable limit) as per BIS 10500	Permissible limit (in absence of alternate source) as per BIS 10500	Test result value	Method of Analysis	Remarks
1	Calcium (as Ca)	mg/l	75	200	110.000	FTK	Ok
2	E. coli	CFU/100 ml	Shall not be detectable in any 100 ml sample	No Relaxation	0.000	H2S vial test	Ok
3	Fluoride (as F)	mg/l	1	1.5	0.070	FTK	Ok
4	Free residual Chlorine	mg/l	0.2	1	0.000	FTK	Ok
5	Iron (As Fe)	mg/l	1	No Relaxation	0.100	FTK	Ok
6	Nitrate (as NO3)	mg/l	45	No Relaxation	17.000	FTK	Ok
7	pH	NA	6.5-8.5	No Relaxation	7.400	Instrumental method	Ok
8	TDS	mg/l	500	2000	397.000	Instrumental method	Ok
9	Total Hardness (As CaCO3)	mg/l	200	600	185.000	FTK	Ok
10	Turbidity	NTU	1	5	0.990	Nephelometric method	Ok

Note:

1)*indicates parameters that are NABL accredited.

2)This test results related to the sample tested above

3)The report shall not to be reproduced in full without approval of authority

4)This is the end of the report

Data prepared by

Chemist: (Dr.Sudarshan Kumar)

Microbiologist: (Dr.Sudarshan Kumar)

Authorised signatory

Dr. Sudarshan Kumar (Test Lab Incharge)

******This is an electronically generated report and does not require a signature.******

Jal Jeevan Mission aims at potable tap water supply to every home

Let's join hands to ensure drinking water is potable. It helps in preventing water borne diseases and improve public health.

Designed & Developed by NIC. Copyright ©copy NJJM 2026

Print

Jal Jeevan Mission

Har Ghar Jal

Har Ghar Jal
Jal Jeevan Mission

S.D. Water Testing Laboratory, Naushera

Sub division Office, Jal Shakti Department, Naushera. Pin-185151 (Test Address only)

Download Print

Test report

Sample Id:	U722368S34780950

User Information

Name:	Vinod Kumar	Mobile:	9697120918
Email:	lichensremedies@gmail.com	Pin Code:	0
Full Address:	Village- Not available , Gram Panchayat- Not available, Block- Not available, District- Rajouri, State- Jammu & Kashmir		

Sample description

Source of Sample:	Others, location :	Village:	Bhajwal
Gram Panchayat:	LOWER BHAJWAL-A	Block:	Sunderbani
District:	Rajouri	State:	Jammu & Kashmir
Address:		Remarks:	DRINKING WATER KV SCHOOL SUNDERBANI
Latitude:	33.156568	Longitude:	74.241945

Date & time of sample collection

12.02.2026 | 10:09:00 AM

Date & time of sample received in lab

12.02.2026 | 06:47:00 PM

Date & time of sample analysed

13.02.2026 | 06:51:00 PM

Date & time of report generation

16.02.2026 | 06:54:17 PM

Test results

S. No.	Parameters tested	Unit of measurement	Requirement (acceptable limit) as per BIS 10500	Permissible limit (in absence of alternate source) as per BIS 10500	Test result value	Method of Analysis	Remarks
1	Calcium (as Ca)	mg/l	75	200	105.000	FTK	Ok
2	E. coli	CFU/100 ml	Shall not be detectable in any 100 ml sample	No Relaxation	0.000	H2S vial test	Ok
3	Fluoride (as F)	mg/l	1	1.5	0.080	FTK	Ok
4	Free residual Chlorine	mg/l	0.2	1	0.000	FTK	Ok
5	Iron (As Fe)	mg/l	1	No Relaxation	0.100	FTK	Ok
6	Nitrate (as NO3)	mg/l	45	No Relaxation	23.000	FTK	Ok
7	pH	NA	6.5-8.5	No Relaxation	7.300	Instrumental method	Ok
8	TDS	mg/l	500	2000	298.000	Instrumental method	Ok
9	Total Hardness (As CaCO3)	mg/l	200	600	193.000	FTK	Ok
10	Turbidity	NTU	1	5	0.780	Nephelometric method	Ok

Note:

1)*indicates parameters that are NABL accredited.

2)This test results related to the sample tested above

3)The report shall not to be reproduced in full without approval of authority

4)This is the end of the report

Data prepared by

Chemist: (Dr.Sudarshan Kumar)

Microbiologist: (Dr.Sudarshan Kumar)

Authorised signatory

Dr. Sudarshan Kumar (Test Lab Incharge)

******This is an electronically generated report and does not require a signature.******

Jal Jeevan Mission aims at potable tap water supply to every home

Let's join hands to ensure drinking water is potable. It helps in preventing water borne diseases and improve public health.

Designed & Developed by NIC. Copyright ©copy NJJM 2026

Print

APPENDIX -IX

MANDATORY PUBLIC DISCLOSURE

A : GENERAL INFORMATION :

SL NO.	INFORMATION	DETAILS
1	NAME OF THE SCHOOL	K V BSF CAMPUS SUNDERBANI DT RAJOURI J&K
2	AFFILIATION NO.(IF APPLICABLE)	700035
3	SCHOOL CODE (IF APPLICABLE)	24950
4	COMPLETE ADDRESS WITH PIN CODE	KENDRIYA VIDYALAYA, BSF CAMPUS, SUNDERBANI DT, RAJOURI, - 180004
5	PRINCIPAL NAME	Mr Amit Kumar
6	PRINCIPAL QUALIFICATION	BEd, MSC (Maths)
7	SCHOOL EMAIL ID	kvsunderbani@gmail.com
8	CONTACT DETAILS (LANDLINE/MOBILE)	01960233268

B : DOCUMENTS AND INFORMATION:

SL NO.	DOCUMENTS/INFORMATION	LINKS OF UPLOADED DOCUMENTS ON YOUR SCHOOL'S WEBSITE
1	COPIES OF AFFILIATION/UPGRADATION LETTER AND RECENT EXTENSION OF AFFILIATION, IF ANY	https://bsfsunderbani.kvs.ac.in/en/cbse-mandatory-public-disclosure/
2	COPIES OF SOCIETIES/TRUST/COMPANY REGISTRATION/RENEWAL CERTIFICATE, AS APPLICABLE	https://bsfsunderbani.kvs.ac.in/en/cbse-mandatory-public-disclosure/
3	COPY OF NO OBJECTION CERTIFICATE (NOC) ISSUED, IF APPLICABLE, BY THE STATE GOVT./UT	

4	COPIES OF RECOGNITION CERTIFICATE UNDER RTE ACT, 2009, AND IT'S RENEWAL IF APPLICABLE	https://bsfsunderbani.kvs.ac.in/en/cbse-mandatory-public-disclosure/
5	COPY OF VALID BUILDING SAFETY CERTIFICATE AS PER THE NATIONAL BUILDING CODE	https://bsfsunderbani.kvs.ac.in/en/cbse-mandatory-public-disclosure/
6	COPY OF VALID FIRE SAFETY CERTIFICATE ISSUED BY THE COMPETENT AUTHORITY	https://bsfsunderbani.kvs.ac.in/en/cbse-mandatory-public-disclosure/
7	COPY OF THE SELF CERTIFICATION SUBMITTED BY THE SCHOOL FOR AFFILIATION/UPGRADATION/EXTENSION OF AFFILIATION	https://bsfsunderbani.kvs.ac.in/en/cbse-mandatory-public-disclosure/
8	COPIES OF VALID WATER, HEALTH AND SANITATION CERTIFICATES	https://bsfsunderbani.kvs.ac.in/en/cbse-mandatory-public-disclosure/

NOTE:

THE SCHOOLS NEEDS TO UPLOAD THE SELF ATTESTED COPIES OF ABOVE LISTED DOCUMETNS BY CHAIRMAN/MANAGER/SECRETARY AND PRINCIPAL. IN CASE, IT IS NOTICED AT LATER STAGE THAT UPLOADED DOCUMENTS ARE NOT GENUINE THEN SCHOOL SHALL BE LIABLE FOR ACTION AS PER NORMS.

C : RESULT AND ACADEMICS :

SL NO.	DOCUMENTS/INFORMATION	LINKS OF UPLOADED DOCUMENTS ON YOUR SCHOOL'S WEBSITE
1	FEE STRUCTURE OF THE SCHOOL	https://bsfsunderbani.kvs.ac.in/en/fee-structure/
2	ANNUAL ACADEMIC CALENDER	https://bsfsunderbani.kvs.ac.in/en/result-analysis/

3	LIST OF SCHOOL MANAGEMENT COMMITTEE (SMC)	https://bsfsunderbani.kvs.ac.in/en/vidyalaya-mangement-committee/
4	LIST OF PARENTS TEACHERS ASSOCIATION (PTA) MEMBERS	https://bsfsunderbani.kvs.ac.in/en/cbse-mandatory-public-disclosure/
5	LAST THREE-YEAR RESULT OF THE BOARD EXAMINATION AS PER APPLICABILITY	https://bsfsunderbani.kvs.ac.in/en/result-analysis/

D : STAFF (TEACHING) :

SL NO.	INFORMATION	DETAILS
1	PRINCIPAL	Mr Amit Kumar
2	TOTAL NO. OF TEACHERS	27
	PGT	7
	TGT	7
	PRT	12
3	TEACHERS SECTION RATIO	1:1.5
4	DETAILS OF SPECIAL EDUCATOR	0
5	DETAILS OF COUNSELLOR AND WELLNESS TEACHER	0

RESULT CLASS: X

SL NO.	YEAR	NO. OF REGISTERED STUDENTS	NO. OF STUDENTS PASSED	PASS PERCENTAGE	REMARKS
1	2026	36	36	100	

RESULT CLASS: XII

SL NO.	YEAR	NO. OF REGISTERED STUDENTS	NO. OF STUDENTS PASSED	PASS PERCENTAGE	REMARKS
1	2026	18	18	100	

E : SCHOOL INFRASTRUCTURE:

SL NO.	INFORMATION	DETAILS
1	TOTAL CAMPUS AREA OF THE SCHOOL (IN SQ MTR)	16000
2	NO. AND SIZE OF THE CLASS ROOMS (IN SQ MTR)	24 & 30
3	NO. AND SIZE OF LABORATORIES INCLUDING COMPUTER LABS (IN SQ MTR)	6 & 50
4	INTERNET FACILITY	YES
5	NO. OF GIRLS TOILETS	6
6	NO. OF BOYS TOILETS	6
7	LINK OF YOUTUBE VIDEO OF THE INSPECTION OF SCHOOL COVERING THE INFRASTRUCTURE OF THE SCHOOL	https://www.youtube.com/@kvsunderbani-onlinestudy7992

F : TEACHER DETAILS:

SL NO.	TEACHER NAME	DESIGNATION	QUALIFICATION
1	SANDEEP SHARMA	PRT	B.TECH
2	RINKI DHADWAL	PRT	P.Grad
3	SATISH KUMAR	TGT	B.SC, B.ED
4	RAKHI SHARMA	PGT	B.SC
5	GULSHAN KUMAR	PGT	M.SC
6	RAM NARESH MEENA	PGT	MA

7	MANISH KUMAR	PGT	B.E.
8	MANOJ KUMAR	TGT	POST GRDAUTION
9	shaileshwari nabiyal	TGT	POST GRDAUTION
10	SANJEEV SHARMA	PGT	POST GRDAUTION
11	AKSHAY KUMAR	TGT	POST GRDAUTION
12	SHEVANI SHARMA	PGT	MSC
13	JYOTI SHARMA	TGT	MA