

## Annexure C

### PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. BIOM-Kdl.Comp/Civil/5534/2024

Dated: 12.04.2024

It is certified that an inspection team headed by Shri. S.P. Raju, Sr. Manager (Civil) (Name of Officers with designation) from NMDC Limited, Civil Department, Water Supply Section inspected the Kendriya Vidyalaya, Kirandul, BIOM Kirandul, Dist- Dantewada, Chhattisgarh-494556 (Name & Address of the school) on 12.04.2024 (date of inspection) and on the basis of Water Test Report (Attached) bearing no. NMDC/LAB/RG-11/VOL-IV/112/890 dated 06/03/2024 of Chemical Lab, NMDC Limited, BIOM Kirandul Complex certified that the Kendriya Vidyalaya, Kirandul (Name of school) has safe drinking water facilities for the students and members of staff of the institution. School is also maintains the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/State/ U.T. Govt.

This certificate is valid till Five (05) Years.

  
12/04/2024  
वरिष्ठ प्रबंधक (सिविल)  
Sr. Manager (Civil)  
बी.आई.ओ.एम., किरन्दुल कॉम्प्लेक्स  
B.I.O.M. Kirandul Complex

Name: Shri. S.P. Raju  
Designation: Sr. Manager

Name & Address of Department/ Office: Civil Engineering Department  
NMDC Limited, BIOM Kirandul Complex

To

Kendriya Vidyalaya,  
BIOM Kirandul,  
Dist- Dantewada,  
Chhattisgarh-494556

(Name & Address of the Institution)

Note: The certificate is to be issued by authorized officer/PHED Lab/local bodies