

Annexure D

BUILDING SAFETY CERTIFICATE

No. BIOM-Kdl.Comp/Civil/533/2024

Dated: 12.04.2024

It is certified that the existing building Kendriya Vidyalaya, Kirandul (name of the building or premises) at NMDC Township, BIOM, Kirandul Complex (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	02	02	NA	NA	NA	NA

The building is owned/occupied by Kendriya Vidyalaya, Kirandul (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of NMDC Limited, Civil Department (Name of Department/ Govt.) on 12.04.2024 (date of inspection) in the presence of Shri. S.P. Raju, Sr. Manager (Civil) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 12.04.2024 for a period of Five (05) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Year of construction of building 2022

Issued on 12.04.2024 at Kirandul by


वरिष्ठ प्रबंधक (सिविल)
Sr. Manager (Civil)
बी.आई.ओ.एम., किरन्दुल कॉम्प्लेक्स
B.I.O.M. Kirandul Complex

Name: Shri. S.P. Raju
Designation: Sr. Manager
Name & Address of Department/ Office: Civil Engineering Department
NMDC Limited, BIOM Kirandul Complex