

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 29/08/2026

It is certified that the existing building Kendriya Vidyalaya, (name of the building or premises) at NMDC Township, B.I.O.M., Kirandul Complex (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2	G+2	—	—	—	—

The building is owned/occupied by NMDC/Kendriya Vidyalaya, Kirandul (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Kirandul, NMDC Limited (Name of Department/ Govt.) on 29/08/26 (date of inspection) in the presence of K. Suresh Kumar, Sr. Mgr (Civil), Kirandul (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 29/08/26 for a period of one year years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Year of Building Construction (2022) (G+1) floors
2. Second floor Constructed in June 2026
- 3.
- 4.

Issued on 29/8/26 at Kirandul by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name : K. Suresh Kumar
Designation : Sr. Mgr (Civil)

Name & Address of Department/ Office:

NMDC Works - Kirandul

66 | Page

क. सुरेश कुमार
K. SURESH KUMAR
वरि. प्रबंधक (सिविल) कार्य
Sr. Manager (Civil) Works
बी.आई.ओ.एम., किरंदुल कॉम्प्लेक्स
B.I.O.M Kirandul Complex