

## CERTIFICATE

A visual observation of the school building of Kendriya Vidyalaya No.2 Binnaguri Cantt. was carried out by the representative of this office and found out that there were no cracks and settlement of walls/ground anywhere in the building of Kendriya Vidyalaya No.2 (South Zone) Binnaguri Cantt. The building is already in use and can be used further for school purpose. This certificate will be valid for a period of one year from the date of its issue.

Station Binnaguri

Date: 06/06/24

Assistant Garrison Engineer (South)

**S S Bandyopadhyay**  
AE (Civ)  
AGE B/R-I(s) Binnaguri