


6 20

SAFETY - CERTIFICATE

It is certified that Kendriya Vidyalaya Building Principal Residence (D-1), staff quarter Block of Four (B-01 to B-04), Staff quarter Block four (C-01 to C-04) have been inspected visually and No cracks/sinking in floor seen. Building is structurally safe as on 04.01.2024.

Sanitary fitments required minor maintenance in school building.



*(Handwritten signature)*  
JEEER)