स्वच्छ भारत
एक कदम स्वच्छता की ओर

भारत सरकार
कार्यपालक अभियन्ता कार्यालय
गुवाहाटी मंडल, के लो नि वि
बामुनीमैदान, गुवाहाटी -७८१०२१

Government of India
O/o the Executive Engineer,
Guwahati Division, CPWD
Bamunimaidan, Guwahati – 781021

e-mail Id: eegcdcpwd.ghy@gov.in/eegcdghy@gmail.com

मि॰ संख्या. 23(384)/कार्यपालक अभियंता, गु.मंडल/2025-26/708(हि.) दिनांक: 13 /05 /2025

सेवामें / To

The Principal
Kendriya Vidyalaya, Goalpara
Near Main Post Office,
Bhalukdubi, Goalpara-783101

बीषय: /Subject: Building Safety Certificate

संदर्भ /Ref.: Your Letter Nos. (i) F.No.084/Misc/KVG/2025-26/05 dated 24.04.2025

महोदय /Sir

Enclosed please find herewith the safety certificate of the 'A Type School Building for K.V. at Goalpara (Assam), duly counter signed by the undersigned as desire by you vide above referred letter.

संग्लन / Encl: Safety Certificate in original.

भवदीय

(ई. दि. शा. ठाकुर)
कार्यपालक अभियंता/ Executive Engineer,
गुवाहाटीमंडल, Guwahati Division
के॰ लो . नि॰ बि॰, गुवाहाटी-21
CPWD, Guwahati-21

Copy to
1. The Assistant Engineer, RBI Project Sub Division-I, CPWD, Guwahati (Assam) for inforamtion .

Executive Engineer, Guwahati

BUILDING SAFETY CERTIFICATE

Name of the Building: **'A' Type School Building for Kendriya Vidyalaya at Goalpara (Assam)**

To Whom It May Concern

It is certified that, the construction of the above mentioned building was completed in January'2015 and handed over in June'2015 by C.P.W.D. It was constructed as per CPWD Specification and IS Codes. The Maintenance of the building is carried out by KV administration since June' 2015. During the site inspection on **dated 02.05.2025** by the concerned Assistant Engineer and Junior Engineer, it is found that, there are minor plaster cracks observed in few class rooms and same may be rectified. However, the building is structurally sound and safe for use.

Assistant Engineer
RBI Project Sub Division-I
CPWD, Guwahati (Assam)

Executive Engineer,
Guwahati Division
CPWD, Guwahati-21

15-5-25