

Tele: 22327065 (Civ). 6556 (Army)  
E Mail : stm4-mes@nic.in

Garrison Engineer  
St Thomas Mount  
Rudra Road  
Old MH Complex  
Chennai - 16

Jul 2024 2202!

KV DGQA  
Palavanthangal  
Chennai-061

REQUEST TO ISSUE STRUCTURAL SAFETY CERTIFICATE FOR THE SCHOOL  
BUILDINGS OF KV DGQA

1. Ref your office letter F. School Building/KVDGQA/2024-25 dt 06 Jul 2024.
2. On visual inspection, it is opined that, the Kendriya Vidyalaya buildings at Palavanthangal have been found structural safe. However, the following are suggested to enhance the life of buildings  
(a) Vegetation/small shrubs found on the roof and wall surfaces at certain location of the buildings to be removed regularly.
3. This if for your info and necessary action please.

15/07/24

(SK Verma, IDSE)

Garrison Engineer

*Muramath*  
18/03/2028  
प्राचार्य / Principal  
के एच की केन्द्रीय विद्यालय  
PM SHRI KENDRIYA VIDYALAYA  
के. वी. क्यू. ए / D.G.Q.A.  
पलवन्थान्गल डा.ए. / Palavanthangal P.O.  
चेन्ने-६१ / Chennai-600 061.

Old MH Complex Chennai 16

2202/

2024

KV OGQA

Pala,vanthangat  
Chennai-061

BUILDINGS OF KV DGQA

REQUEST TO ISS1

STRUCTUR

SAFE

CERTIFICATE

FOR THE SCHO

School Building(WDGQA/2024-Z5

1. Ref your office letter No F
2. On visual inspection, have been found structural safe-buildings :-

06 2024.

it is opined that, the Kendrŷya

Vidyalaya buildirtgs at

However, the foltowäng are suggested to enhance the

(a) Vegetationismat) shrubs found on the roof and wall surfaces at certarn location buildings to be removed regularly.

3 This L<sup>f</sup> for your info and necessary action please,

(SK Verma, IDSE)  
EE  
Garrison Engineer

15/7/24

*Shubam*

प्राचार्य / Principal  
पी एम की केन्द्रीय विद्यालय  
PM SHRI KENDRIYA VIDYALAYA  
डी. जी. क्यू. ए / D.G.Q.A.  
पलवन्तांगल डा.प. / Palavanthangal P.O.  
चेन्नै-६१ / Chennai-600 061.