

CLW/Chittaranjan

AEN(II) /Misc.

Date: 27 /10/2025


Kendriya Vidyalaya
Chittaranjan

Sub: Safety Certificate of Vidyalaya Building and Staff Qrts

Ref: Your letter No F-25112/Nirman/CMSRI/25-26/KVC/397 dated 09/10/2025

As requested vide your letter under reference, visual inspection is done on your school building and staff Qrts. and this is to certify that from visual inspection, it is observed that Kendriya Vidyalaya including staff Qrts seems structurally serviceable and safe.

This is for your information and necessary action please.


सहायक इंजीनियर-II (II)
Asstt. Engineer (II)
वि.रे. का. /वित्त/जन/CLW/CRJ