



GOVERNMENT OF WEST BENGAL,
DIRECTORATE OF PUBLIC HEALTH ENGINEERING,
OFFICE OF THE EXECUTIVE ENGINEER,
SILIGURI WATER SUPPLY DIVISION,
DISTRICT LABORATORY AT FULBARI,
SILIGURI

PHYSICAL AND CHEMICAL TEST REPORTS :


Date Of Collection	20.08.2024
Date Of Analysis	20.08.2024
Date Of Reporting	21.08.2024


SL. NO.	Parameters	Acceptable Limit (as per IS 10500 : 2012)	Cause of Rejection	RESULT	
				Place	Kendriya Vidyalaya BSF Baikunthpur, Salugara
				Source	R.O. Water
				Sender	Principal, Kendriya Vidyalaya BSF Baikunthpur
1.	Turbidity (NTU)	1	5		0.28
2.	pH	6.5 to 8.5	No Relaxation		7.04
3.	TDS(ppm)	500	2000		101
4.	Iron (mg/l)	1.0	No Relaxation		<0.05
5.	Res. Chlorine (mg/l)	0.2	1.0		0
6.	Fluoride (mg/l)	1.0	1.5		0
7.	Total Hardness(mg/l)	200	600		60
8.	Total Alkalinity(mg/l)	200	600		48
9.	Nitrate (mg/l)	45	No Relaxation		<1.0
10.	Copper (mg/l)	0.05	1.5		0
11.	Chloride (mg/l)	250	1000		7

*The tests done with the Sample as deposited by the Party.

Physical & Chemical Test Charge Rs. 900.00/-

Received Vide GRN No. 192024250157731511 Dated : 08/08/2024 .


Chemist/Bacteriologist,
District Laboratory,
Fulbari, W.T.P.



Junior Engineer,
Siliguri Water Supply Division,
P.H. Engineering Dte.


Memo No. 2173/SWSD /SD: Dated, Siliguri, the 22.08. 2024

Copy forwarded for information and necessary action to:-

1. Principal, Kendriya Vidyalaya BSF Baikunthpur .
2. Office Copy.

Report No: Chem/2024/Aug-27


Assistant Engineer-I,
Siliguri Water Supply Division,
P.H. Engineering Dte.


K.V. BSF Baikunthpur
Receipt No. 126 / File No. 379
Date 21/8/24



GOVERNMENT OF WEST BENGAL,
DIRECTORATE OF PUBLIC HEALTH ENGINEERING,
OFFICE OF THE EXECUTIVE ENGINEER,
SILIGURI WATER SUPPLY DIVISION,
DISTRICT LABORATORY AT FULBARI,
SILIGURI

BACTERIOLOGICAL ANALYSIS :

Date Of Collection	16.08.2024
Time Of Collection	01.05 PM
Date Of Analysis	16.08.2024 TO 17.08.2024
Date Of Reporting	17.08.2024

Sl No.	Bacteriological Parameters	Acceptable Limit	RESULT	
			Place	Kendriya Vidyalaya BSF Baikunthpur, Salugara
			Source	R.O. Water
			Sender	Principal, Kendriya Vidyalaya BSF Baikunthpur
1.	Total Coliform Present/Absent (CFU/100 ML)	Absent		ABSENT
2.	Faecal Coliform Present/Absent (CFU/100 ML)	Absent		ABSENT
3.	WATER BACTERIOLOGICALLY SAFE/UNSAFE	--		SAFE

*The tests done with the Sample as deposited by the Party.

Bacteriological Test Charge Rs. 500.00/-

Received Vide GRN No. 192024250157731511 Dated : 08/08/2024 .

T.D.
Chemist/Bacteriologist,
District Laboratory,
Fulbari, W.T.P.

[Signature]
Junior Engineer,
Siliguri Water Supply Division,
P.H. Engineering Dte.

Memo No.....2174 /SWSD...../SD: Dated, Siliguri, the...22.08.....2024

Copy forwarded for information and necessary action to:-

1. Principal, Kendriya Vidyalaya BSF Baikunthpur .
2. Office Copy

Report No: Bact/2024/Aug-21

[Signature]
Assistant Engineer-I,
Siliguri Water Supply Division
P.H. Engineering Dte.