



भारतीय प्रौद्योगिकी संस्थान खड़गपुर
खड़गपुर - 721 302, भारत

Indian Institute of Technology Kharagpur
Kharagpur - 721302, India

सिविल निर्माण एवं अनुरक्षण विभाग / CIVIL CONSTRUCTION AND MAINTENANCE SECTION

No.: IIT/CCM/KV/2024-25/D-15342

Date : 07.01.2025

THE PRINCIPAL

PM SHRI KENDRIYA VIDYALAYA NO. 1, IIT KHARAGPUR
IIT CAMPUS, KHARAGPUR
PASCHIM MEDINIPUR, WEST BENGAL

SUB : Structural safety of PM Shri Kendriya Vidyalaya No. 1 at IIT Kharagpur Campus

REF : Your letter No. F-25350/1260/KV(IIT)Kharagpur/24-25/335 dated 09.12.2024

Dear Madam,

With reference to your above-mentioned letter, it is to mention that during visual inspection of the Kendriya Vidyalaya building on 24.12.2024 no structural stability issues were observed.

Thanking you.

Yours sincerely,

(Arindam Mukherjee)
Executive Engineer (Civil)

Copy for kind information to :

1. Dean, Infrastructure, IIT Kharagpur
2. Chief Engineer, IIT Kharagpur
3. Superintending Engineer (Civil), IIT Kharagpur