CERT. NO.: BRBNML/03-2024/1482

CERTIFICATE OF STABILITY

1. Name of Factory

: BHARATIYA RESERVE BANK NOTE MURDAN (P)

LIMITED

2. Village, Town and District in which the Factory is Situated

: Paschim Medinipur, Pin - 721132

3. Full Postal Address of the Factory

: BHARATIYA RESERVE BANK NOTE MURDAN (P)

LIMITED

P. O. - R.B.N.M.L, Salboni, Paschim Medinipur, P. S. - Salboni, Sub Divisional Head Quarter- Paschim Medinipur Sadar, Pin - 721132, West Bengal

4. Name of the Occupier of the Factory : SHRI K. S. P. MARAN PANDIAN

5. Nature of the manufacturing Process to be carried on in The Factory

: Printing & Dispatch of Bank Notes

Number of floor on which Workers will : As per Plan be employed

I certify that I have inspected the Buildings/Sheds (List of inspected areas are enclosed), the plans of which have been approved by the Chief Inspector in his Letter No.: 515/P, Dated: 22.08.1994, (with approved Plan No. MEC/0989/II/19/48/0028/R04, Dated: 12.07.1994 Registration No.: 0003/MD/X/ 1996 and License No.: 013905, Dated: 11.12.1996) and examined the various parts including the foundations with special reference to the Machine, Plant etc., that have been installed. I am of the opinion that the Buildings/Sheds which have been constructed/ reconstructed/extended/taken into use is/are in accordance with the plans approved by the Chief Inspector in his Letter mentioned above, that they are structurally sound and that its/their stability will not be endangered by their use as Factory/part of a Factory for the manufacturing of Printing & Dispatch of Bank Notes for which the machinery, plant, etc. installed are intended.

NB: ABOVE INFORMATION TAKEN BY BHARATIYA RESERVE BANK NOTE MURDAN (P) LIMITED



Competent Person Under Factories Act, 1948

NB: The Certificate format as per Guideline of DGFASLI (Corrected upto 31/03/1987)

Continued to page - 2

LIST OF INSPECTED BUILDINGS/SHEDS/STRUCTURES/FOUNDATIONS

SI. No.	NAME OF THE BUILDINGS/SHEDS/ STRUCTURES/FOUNDATIONS	OBSERVATIONS AS ON DATE
1.	Administrative Building	It appears from visual observation and Non-
		Destructive Tests of Concrete, the Building
		(as on date) appears to be satisfactory.
2.	Community Centre	It appears from visual observation and Non-
		Destructive Tests of Concrete, the Building
		(as on date) appears to be satisfactory but in
		community Centre deep cracks have been
		observed in between plinth protection and
		building wall joints in the sides and back
		portion. Need to be repaired immediately.
3.	Kendriya Vidyalaya Building and	It appears from visual observation and Non-
	Canopy	Destructive Tests of Concrete, the Building and
		Canopy (as on date) appears to be satisfactory.
4.	Quarter No. D 18/2 and D 18/4	It appears from visual observation and Non-
		Destructive Tests of Concrete, the Building
		(as on date) appears to be satisfactory but
		front Balcony Area Column & Beam have been
		observed major cracks. Need to be repaired
		immediately.

Examination, Inspection and issuing Certificate of Stability with respect to Buildings/Sheds as stipulated under section 112 under the Factories Act 1948 with special reference to Sec 39, 40 and Rule 2A, 3A © of West Bengal Factories Rules 1958.

Date of Inspection – 27th & 29th March 2024.

- Maintenance work is to be done time to time.
- Routine maintenance schedule to be attended too.
- · Maintain Register for the above.
- Adopting all Safety Compliances during maintenance work.

S A S

SANTANU DATTA
B.E. (Civil)
Competent Person
Under Factories Act, 1948