



भारत सरकार  
केंद्रीय लोक निर्माण विभाग  
कार्यपालक अभियंता  
त्रिपुरा-I, कें. लो.नि. वि.

GOVERNMENT OF INDIA  
CENTRAL PUBLIC WORKS DEPARTMENT  
OFFICE OF THE EXECUTIVE ENGINEER  
TRIPURA -I , CPWD



कें. लो.नि. वि. परिसर, उषाबाजार, अगरतला-09 C.P.W.D. Complex, Usha Bazar, Agartala-09

File No.DB(3)/TCD-1/AGT/2024/ 1149

Dated: - 25 /10/2024

To  
The principal  
KV Kailasahar  
Unakoti, Tripura

Reference: Letter No. 1-2/L&B/KV-KLS/2024-25/220 Dated: 29.07.2024

### Building Safety Certificate

It is certified that Kendriya Vidyalaya Kailasahar, Unakoti, Tripura was inspected visually on date 03.08.2024 along with Assistant Engineer and found that above Building seems to be normal in Natural Conditions superficially.

(Note:-This Certificate may not be used for structural soundness of above building as structural soundness can be assessed by Specialized Agency only).

*Kumar*

Junior Engineer  
TCSD-IV/EE (Tripura-I),  
CPWD, Agartala.

*[Signature]*

Assistant Engineer  
TCSD-IV/EE (Tripura-I),  
CPWD, Agartala.

*[Signature]*

Executive Engineer  
EE (Tripura-I)  
CPWD, Agartala.