



भारत सरकार

Government of India

केंद्रीय लोक निर्माण विभाग

Central Public Works Department

कार्यपालक अभियन्ता का कार्यालय, गुवाहाटी मंडल

Office of the Executive Engineer, Guwahati Division

निर्माण भवन, बामुनीमैदान, गुवाहाटी -781021

Nirman Bhawan, Bamunimaldan, Guwahati-781021

(e-mail : eegcdcpwd.ghy@gov.in/eegcdghy@gmail.com)



मि संख्या. 23(481)/कार्यपालक अभियन्ता, गु. मंडल/06 (दि)

दिनांक: 02/01/2024

TO WHOM IT MAY CONCERN

It is certified that the School Building of Kendriya Vidyalaya at Nagaon, Assam had been inspected by the undersigned along with the Assistant Engineer, Shri Mukesh Kr. Choudhari, Assistant Engineer, Guwahati Sub Division, CPWD, Guwahati on dated **22.12.2023**. During the Inspection no noticeable defects are found and the infrastructures are structurally safe as on date.

सेवा में

✓ The Principal

PM Shri Kendriya Vidyalaya, Nagaon

P.O. Itachali, Dist: Nagaon (Assam)

Pin-782003

Email: kvnagaon1484@gmail.com

संदर्भ: Your letter No. 24-2023/KVN/20046/363 dated 20.12.2023

भवदीय

(ई. दि. शा. ठाकुर)

कार्यपालक अभियन्ता, गुवाहाटी मंडल
के. लो. नि. वि., गुवाहाटी-२१

21-14

Copy to:

1. The Chief Engineer, Guwahati, CPWD, Garchuk, Guwahati -781035 for favour of kind information please.
2. The Assistant Engineer, Guwahati Sub Division, CPWD, Guwahati for information.

कार्यपालक अभियन्ता