

APPENDIX-VIII

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY
CONDITION CERTIFICATE

No. PNP /Health /2023/545

Dated: - 11-7-2023

It is certified that an inspection team headed by Dy. Civil Surgeon (H) and Sh. Satish Kumar Health Inspector (Name of Officers with designation) From Civil Surgeon Office Panipat (Name of Department / Office) inspected the Kendriya vidyalaya, Vill. Beholi, Distt. Panipat inspected on 06/07/2023 and found that the Kendriya vidyalaya, Vill. Beholi, Distt. Panipat has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus.

The above valid for a period of One Year.

Bajwa →
Dy. Civil Surgeon (H)
Civil Surgeon (Panipat)
11/7/23

To
Kendriya vidyalaya,
Vill. Beholi,
Distt. Panipat